

ARRIVAL ROUTE DESCRIPTION

BORGER TRANSITION (BGD.UKW1): From over BGD VORTAC via BGD R-117 to HEATR INT, then via SPS R-299 to SPS VORTAC, then via SPS R-115 and UKW R-299 to UKW VORTAC. Thence. . . .

GUTHRIE TRANSITION (GTH.UKW1): From over GTH VORTAC via GTH R-063 to ZANTO INT, then via UKW R-283 to UKW VORTAC. Thence. . . .

PANHANDLE TRANSITION (PNH.UKW1): From over PNH VORTAC via PNH R-097 to HEATR INT, then via SPS R-299 to SPS VORTAC, then via SPS R-115 and UKW R-299 to UKW VORTAC. Thence. . . .

TEXICO TRANSITION (TXO.UKW1): From over TXO VORTAC via TXO R-086 to GANJA INT, then via UKW R-283 to UKW VORTAC. Thence. . . .

TULSA TRANSITION (TUL.UKW1): From over TUL VORTAC via TUL R-209 to MOOSE INT, then via UKW R-015 to UKW VORTAC. Thence. . . .

WICHITA FALLS TRANSITION (SPS.UKW1): From over SPS VORTAC via SPS R-115 and UKW R-299 to UKW VORTAC. Thence. . . .

WILL ROGERS TRANSITION (IRW.UKW1): From over IRW VORTAC via IRW R-166 to MOOSE INT, then via UKW R-015 to UKW VORTAC. Thence. . . .

. . . . ALL AIRCRAFT: From over UKW VORTAC via UKW R-129 and TTT R-310. Thence. . . .

. . . . ALL AIRCRAFT LANDING SOUTH: To HIKAY INT, expect vectors to final approach course.

. . . . RNAV CAPABLE JETS LANDING NORTH: From over SILER INT direct ARODD WP, expect vectors to final approach course prior to ARODD WP. If not received by ARODD WP fly present heading. DME/DME/IRU or GPS required. Pilots of RNP capable aircraft use RNP 2.0. Type B.

. . . . PROPS LANDING NORTH: To HIKAY INT, depart HIKAY INT heading 145° for vector to final approach course.

. . . . ALL OTHERS: To SILER INT depart SILER INT heading 175° for vector to final approach course.

SC-2, 25 AUG 2011 to 22 SEP 2011

SC-2, 25 AUG 2011 to 22 SEP 2011