25 FEB 2021 to 25 MAR 2021

HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

holding position markings CARLSBAD, CA MC CLELLAN-PALOMAR (CRQ) HS 1 Large Jets may obscure twr visibility of small aircraft. HS 2 Exiting Rwy 24 at Twy A4		oon reduc	ed of eliminated.
BOB HOPE (BUR) HS 1 NW corner of terminal ramp close proximity to Rwy 33-15 rw holding position markings CARLSBAD, CA MC CLELLAN-PALOMAR (CRQ) HS 1 Large Jets may obscure twr visibility of small aircraft. HS 2 Exiting Rwy 24 at Twy A4	(PORT HC	OT SPOT	DESCRIPTION*
MC CLELLAN-PALOMAR (CRQ) HS 1 Large Jets may obscure twr visibility of small aircraft. HS 2 Exiting Rwy 24 at Twy A4	HOPE (BUR)	HS 1	NW corner of terminal ramp close proximity to Rwy 33-15 rwy holding position markings
CHINO, CA CHINO (CNO) HS 1 Twy D close proximity to Rwy 08L-26R. HS 2 Twy L close proximity to Rwy 03-21. HS 3 Twy K close proximity to Rwy 08L-26R. HS 4 Twy L, Twy D, and Twy K complex int.		HS 2 HS 3	Twy L close proximity to Rwy 03-21. Twy K close proximity to Rwy 08L-26R.
EL MONTE, CA SAN GABRIEL VALLEY (EMT) HS 1 Twy A at Twy C. HS 2 Twy A at Twy D.	GABRIEL VALLEY (EMT)		, ,
HAWTHORNE, CA JACK NORTHROP FIELD/ HAWTHORNE MUNI (HHR) HS 1 Rwy 25 run-up area.	NORTHROP FIELD/	HS 1	Rwy 25 run-up area.
LANCASTER, CA GENERAL WM J FOX AIRFIELD (WJF) HS 1 Pilots mistake Rwy 06-24 for Twy A.	ERAL WM J FOX	HS 1	Pilots mistake Rwy 06-24 for Twy A.
LA VERNE, CA BRACKETT FIELD (POC) HS 1 Twy A between the apch ends of Rwy 26R and Rwy 26L.	The state of the s	HS 1	Twy A between the apch ends of Rwy 26R and Rwy 26L.
LONG BEACH, CA LONG BEACH (DAUGHERTY FLD) (LGB) HS 1 Rwy 12-30 and Rwy 08L-26R, Twy B and Twy K. HS 2 Rwy 08R-26L, Twy B.	G BEACH (DAUGHERTY		
LOS ANGELES, CA LOS ANGELES INTL (LAX) HS 1 Rwy 24L and Twy AA. HS 2 Rwy 24L and Twy Z. HS 3 Rwy 25 L, Rwy 25 R and Twy F. HS 4 Twy H and Twy H5. HS 5 Twy H, Twy H5, and Twy H6.		HS 2 HS 3 HS 4	Rwy 24L and Twy Z. Rwy 25 L, Rwy 25 R and Twy F. Twy H and Twy H5.
MOJAVE, CA MOJAVE AIR AND SPACE PORT (MHV) HS 1 Rwy 08 and Rwy 04 at Twy C and Twy F. Ensure clearance	AVE AIR AND SPACE PORT	HS 1	Rwy 08 and Rwy 04 at Twy C and Twy F. Ensure clearance
received for each rwy. HS 2 Twy A, Twy C, Twy D intersect. Limited tower visibility.	•	HS 2	received for each rwy.
ONTARIO, CA ONTARIO-INTL (ONT) HS 1 Twy F at Rwy 08R/26L frequent centerline confusion crossir southbound.		HS 1	Twy F at Rwy 08R/26L frequent centerline confusion crossing rwy southbound.
HS 2 Twy P and Twy Q confusing split between rwys southbound		HS 2	Twy P and Twy Q confusing split between rwys southbound.

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

25 FEB 2021 to 25 MAR 2021

HOT SPOTS

		(CONTINUED)
CITY/AIRPORT	HOT SPOT	DESCRIPTION*
PALM SPRINGS, CA		
PALM SPRINGS INTL (PSP)	HS 1 HS 2 HS 3 HS 4	Twy C mistaken for Rwy 13R-31L or Rwy 13L-31R. Int of Twy B and Twy C. Twy B and Rwy 31R. Twy C and Twy J.
RIVERSIDE, CA		
RIVERSIDE MUNI (RAL)	HS 1 HS 2	Twy A and Rwy 34. ATC non-vis area.
SAN DIEGO, CA		
MONTGOMERY FLD (MYF)	HS 1 HS 2 HS 3	Rwy 28R and Rwy 28L, Twy M. Rwy 28L-10R and Rwy 05-23. Rwy 28L and Twy B.
SAN DIEGO INTL (SAN)	HS 1	Twy J at Twy H.
SAN LUIS OBISPO, CA		
SAN LUIS COUNTY RGNL (SBP) HS 1 HS 2	Area directly below the Control Twr "not visible". Twy E, Rwy 29.
SANTA ANA, CA JOHN WAYNE ARPT-	2	, _,,
ORANGE COUNTY (SNA)	HS 1 HS 2 HS 3	Rwy 20L and Twy L. Rwy 20L and Rwy 20R, Twy H. Twy A,Twy H, and Twy C.
SANTA BARBARA, CA		
SANTA BARBARA MUNI (SBA)	HS 1 HS 2	Rwy 07-25, Twy C. Rwy 15L-33R, Rwy 15R-33L, Rwy 07-25. Rwy 15L-33R and Rwy 15R-33L utilized for taxi.
	HS 3	Rwy 25, Twy H and Twy J.
SANTA MARIA, CA		
CAPTAIN G ALLAN HANCOCK		
FLD (SMX)	HS 1 HS 2	Twy A, Twy A7, Twy A8, Twy V, and Twy W. Twy A, Twy A6, Twy A5, Twy R, and Twy S.
	HS 3	Rwy 20 and Twy A.
TORRANCE CA	HS 4	Rwy 12 and Twy B2 and Twy A2.
TORRANCE, CA ZAMPERINI FIELD (TOA)	HS 1	Pilots exiting Rwy 11L-29R sometimes fail to hold short of the Rwy 11R-29L apch hold area on Twy H.
VICTORVILLE, CA		
SOUTHERN CALIFORNIA LOGISTICS (VCV)	HS 1	Wrong rwy departure risk.